

81201 Super Macro Converter I

Care and Maintenance

The following procedures are advised to be followed:

1. The SMC should be rinsed thoroughly in fresh water after each dive.
2. Dry and clean the glass surface of the SMC with the cloth provided.
3. Cover the lens with the provided covers when not in use.
4. DO NOT use any kind of abrasive solutions to clean the glass surfaces.

81201 Super Macro Converter I

Care and Maintenance

The following procedures are advised to be followed:

1. The SMC should be rinsed thoroughly in fresh water after each dive.
2. Dry and clean the glass surface of the SMC with the cloth provided.
3. Cover the lens with the provided covers when not in use.
4. DO NOT use any kind of abrasive solutions to clean the glass surfaces.